

# NOTICE OF COMPLETION AND AUTHORIZATION TO APPLY THE UL MARK



2019-12-17

MS. Y.H. CHOW  
FSP GROUP INC  
22 Jianguo E Rd  
Taoyuan City, 330, TW

Our Reference:	File E190414, Vol X1	Order: 13156241
		Project 4789282795
Your Reference:	SPI-5191203820REV.0	
Project Scope:	UL/CUL Investigation for Switching Power Supply. Models 1) FSP320-60EGA, 2) FSP300-60EGA / SPI300A8AG, 3) FSP250-60EGA / SPI250A8AG employing update standard revision from UL 60950-1, 2nd Edition, 2007-03-27 to UL60950-1, 2nd Ed, 2019-05-09.	

Report Reference Number E190414-A402

Dear MS. Y.H. CHOW:

Congratulations! UL's investigation of your product(s) has been completed under the above Reference Number and the product was determined to comply with the applicable requirements. This letter temporarily supplements the UL Follow-Up Services Procedure and serves as authorization to apply the UL Mark at authorized factories under UL's Follow-Up Service Program. To provide your manufacturer(s) with the intended authorization to use the UL Mark, you must send a copy of this notice to each manufacturing location currently authorized under File E190414, Vol X1.

Records in the Follow-Up Services Procedure covering the product are now being prepared and will be sent in the near future. Until then, this letter authorizes application of the UL Mark for 90 days from the date indicated above.

Additional requirements related to your responsibilities as the Applicant can be found in the document "Applicant responsibilities related to Early Authorizations" that can be found at the following web-site: <http://www.ul.com/EAResponsibilities>

Any information and documentation provided to you involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL.

We are excited you are now able to apply the UL Mark to your products and appreciate your business. Feel free to contact me or any of our Customer Service representatives if you have any questions.

Very truly yours,

Lily Su  
Engineer Project Associate  
Lily.Su@ul.com

Reviewed by:

Bruce A. Mahrenholz  
CPO Director  
Bruce.A.Mahrenholz@ul.com

8935df3d-9d64-4cff-94d2-fe85e09feb5a